



**SMT AFLOAT SERVICES PTE LTD**  
2 Penjuru Place #01-09, 2-8 Penjuru Tech Hub,  
Singapore 608783  
Tel: +65 6464 0380 Fax: +65 6464 0381  
Business / G.S.T. Reg. No.: 202001259R

## PHOTO REPORT

Location : Cat Lai Port, Vietnam  
Job Order No. : SMTA-JO-20-0020


**Subject: Rectification of Cargo Hold Flaps**






SMT carried out tool box meeting, risk assessment and hotwork permit. Standby hotwork and safety equipment on vessel were also prepared on board.



One technician managed to enter the flap and carry out troubleshooting without having to crop any plates



Having checked the situation, we found that the grease residues has hardened and we carry out heating on the cargo hold flap spindle and found to be succesful





**SMT AFLOAT SERVICES PTE LTD**

2 Penjuru Place #01-09, 2-8 Penjuru Tech Hub,  
Singapore 608783

Tel: +65 6464 0380 Fax: +65 6464 0381

Business / G.S.T. Reg. No.: 202001259R

Manually cleaning was done using wire brush to clear the grease residue from spindle.  
Carried out opening and closing of the spindle guide until satisfactory and working condition



The spindle was lubed with vessel supplied lubrication oil and carried out function test with vessel's officers until satisfaction.

Total three cargo hold flaps were done for the rectification.

